2013 BENNINGTON 20' SERIAL NUMBER: 32C313 OUTBOARD 50 HP YAMAHA 4-STROKE, WITH TRAILER

CONDITION:

- · 3 tires on the boat trailer are in need or replacement
- · Awning arms bent on the right side
- Depth finder/location cover had to be Windshield is missing screws
- Visible dents and scratches
- Awning light is loose
- Felt coming off the front bumper boards



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form









2013 BENNINGTON 20' SERIAL NUMBER: 36C313 OUTBOARD 50 HP YAMAHA 4-STROKE, WITH TRAILER

CONDITION:

- · 2 tires on the boat trailer in need of replacement
- Visible dents and scratches
- Windshield is missing screws
- Felt coming off the front bumper boards
- Front deck cap bent, missing rivets
- Prop in rough shape
- Awning light is loose



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form









2013 BENNINGTON 20' SERIAL NUMBER: 38C313 OUTBOARD 50 HP YAMAHA 4-STROKE, WITH TRAILER

CONDITION:

- Spare tire is bad
- · Light connection taped up, is in rough shape
- Front right seat has a small tear
- Awing is bent
- Needs a new battery
- Section of decking is sagging
- Missing boat cover
- Safety cable is frayed



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form







502.898.3517 **(a) (b) (c) (c)**



2013 BENNINGTON 24' SERIAL NUMBER: 47C313 OUTBOARD 50 HP YAMAHA 4-STROKE, WITH TRAILER

CONDITION:

- 3 tires plus the spare for the trailer need replacing
- Dent in left pontoon front and side
- Outside paneling in rough shape, visible dents and scratches
- Felt on front bumper board coming off
- Rear right bunk board is broken
- The front of left rear seat is torn
- Depth Finder does not work
- Awning torn near arms, bent awning arms
- Front gate loose, rivets pulling out



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form







502.898.3517 **(a) (b) (c) (c)**



2013 BENNINGTON 24' SERIAL NUMBER: 48C313 OUTBOARD 50 HP YAMAHA 4-STROKE, WITH TRAILER

CONDITION:

- Trailer light tail taped up, in rough shape
- Front of pontoon bent on the left side
- Outside panels bent heavily on front
- Missing cover awning light
- Front bunk boar/bumpers felt coming off
- 4 of the 5 boat tires need replacement
- Front left seat torn
- Awning torn
- Dead battery
- Front gate loose, rivets pulling out



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form







502.898.3517 **(a) (b) (c) (c)**



BASS BOAT #1

2014, 16' ALUMACRAFT ESCAPE 165CS'

SERIAL NUMBER: **B414**

40HP YAMAHA 4-STROKE, MINNKOTA 55LB THRUST HUMMINGBIRD P175 LOCATOR, SHORELANDER TRAILER

CONDITION:

Prop tips are rough and bent



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form







502.898.3517 **(a) (b) (b) (c) (c)**



BASS BOAT #2

2014, 16' ALUMACRAFT ESCAPE 165CS'

SERIAL NUMBER: H314

40HP YAMAHA 4-STROKE, MINNKOTA 55LB THRUST **HUMMINGBIRD P175 LOCATOR, SHORELANDER TRAILER**

CONDITION:

- · Right side railing is bent
- Spare tire is shot
- Light Harness taped, in rough shape



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form









BASS BOAT #3

2014, 16' ALUMACRAFT ESCAPE 165CS'

SERIAL NUMBER: L314

40HP YAMAHA 4-STROKE, MINNKOTA 55LB THRUST HUMMINGBIRD P175 LOCATOR, SHORELANDER TRAILER

CONDITION:

- Handles on floor need replacing
- Front Tire strap needs replacing
- Spare tire needs replaced
- Dead Battery



SCAN THE QR CODE TO PLACE A BID

Or visit mccoy.armymwr.com and complete the bid submission form







